
## Landfill Inspections

- Characterization of landfill boundaries & thickness
- Identification of contaminant plumes & mapping their movement directions
- Investigating drainage pipes & other conduits
- · Delineating point source of seepage




A. Ismail, BGS, left; & Paul Frisbee, P.E. Anderson & Associates acquiring MASW data



PUT OUR SERVICE TO THE TEST





A 2D resistivity profile of a landfill site

**Contact Us:** 

## **Bara Geophysical Services, LLC**

900 Innovation Drive, Suite I Rolla, MO 65409 573.202.0844 573.466.2575 aelsheikh@barageo.com info@barageo.com

www.barageo.com







